



1 year service



1 year service



5 year service

2001 - Epoxy E-303, MIL-P-24441 F150 & F151, Amerthane.

Most of the Amerthane is gone at 5 years due to poor intercoat adhesion to the epoxy.



2001 - Epoxy E-303, MIL-P-24441
F150 & F151, Amerthane after 9 years
service.



2001 - Vinyl VZ-108, V-106 after 24 years
service.

White area is river scum. There is a minor
amount of rust on the edge of each rib. All
other areas are protected.